SQ610_EN_XX_WE__DS_R01_U_261008_02

Security patch

Android security patch updated :
2026-09-05
https://source.android.google.cn/docs/security/bulletin/2026/2026-09-01?hl=zh-cn
2026-08-05
https://source.android.google.cn/docs/security/bulletin/2026/2026-08-01?hl=zh-cn
2026-07-05
https://source.android.google.cn/docs/security/bulletin/2026/2026-07-01?hl=zh-cn

New features

1. Appmarket_V1.3.9.20260903： Fixed the issue where no callback is received after app installation, which caused installation result reporting failure and stuck download & installation queue when multiple apps are installed concurrently;Fixed abnormal button text display on SQ65B and other devices in pages such as forced download and app update under Settings;Fixed the issue of black text on black background for pop-up prompts on some OS.
2. Added partial UStage 2.0 interfaces:DeviceManagerEx: Added APIs for lock screen media display, enabling usage and diagnostics, sending app content to Android system, showing clipboard access notifications, and certificate management:ApplicationManagerEx: Added location permission mode and precise location toggle by package name:LogManagerEx: Extended log collection duration up to 4 hours.

Resovled issues

1. Optimize the jump function of status bar key mapping.
2. Add flight mode attribute in USDK to disable manual switching
3. In roaming-enabled environments, the device will NOT disconnect Wi-Fi
4. Fixed the issue where the top scan camera emitted light but failed to decode after 366 cycles during camera scan switching stress test on a single device.
5. Fixed the camera scan stress test failure issue by implementing thread recycling for SE2030FR.
6. BatteryInfo_V1.19.20260909 optimized the prompt text for battery charging.

Known issues

1. NFC configurable interface is missing for USDK to perform configurations.