

SQ66_WE__DS__R01_U_260126_02

Security patch

Update Android security patch

2025-12-05

<https://source.android.google.cn/docs/security/bulletin/2025-10-01?hl=zh-cn>

2025-11-05

<https://source.android.google.cn/docs/security/bulletin/2025-11-01?hl=zh-cn>

2025-10-05

<https://source.android.google.cn/docs/security/bulletin/2025-10-01?hl=zh-cn>

New features

None

Resolved issues

1. Automatically retry pairing when pairing fails with Bluetooth printer K419_3235
2. Suppress the system notification "Charging via USB" only for OTG wired connection
3. Keep Bluetooth tethering active after exiting the network sharing page
4. Upgrade USDK to V13.3.13.20251202
5. ScanWedge updated to build 20260112. For Honeywell HS7 scan engine: remove duplicate exposure parameter settings, fix wrong title display for multi-decode setting menu
6. Fix screensaver trigger failure issue: selected screensaver mode does not take effect, and the issue persists even after clearing app data (version:1.4.9.20260115_1708)

Known issues

1. Failed to connect to 802.1X enterprise Wi-Fi in the setup wizard.
2. Third-party apps crash when the input method floating window is shown or hidden.
3. security issue that the device can upgrade itself under sideload mode.